

Vehicle identification number (VIN): WP0ZZZY14PSA32093
Order type: Taycan 4S (MY23) (Y1ADB1)
Model year: 2023

Annotation: The information listed below might not be a complete vehicle history. Only jobs that have been documented within PCSS job management (PQIS) are available. This information may not be transmitted to third parties.
Total warranty repair days (WRD): **39 Day(s)**

Filter settings

Workshop/Recall campaign | OTA campaign | Repair | Maintenance/Inspection | Documentation | Reset Filter

Expand all

Status	Repair Start	Repair End	Dealer	Mileage	
	18/12/2025	18/12/2025	6130010 - Porsche Center Prague	30291 km	5
Campaign			**Location:** Campaign not feasible: WSS6Z Re-programming 12V battery sensor **Symptom:** 6600 Workshop campaign		
Campaign			**Location:** Campaign not feasible: WSD8Z Replace electric passenger compartment heater **Symptom:** 6600 Workshop campaign		
Campaign			**Location:** Campaign not feasible: ARB6Z Checking HVB cell modules and re-programming BMCe software **Symptom:** 9900 Recall campaign		
Maintenance/Inspection			Maintenance		
Maintenance/Inspection			Maintenance: Výměna pyl. filtru, brz. kapaliny.		
	18/12/2025	18/12/2025	6130010 - Porsche Center Prague	30291 km	3
Campaign			**Location:** Campaign complete: WSD82 Replace electric passenger compartment heater **Symptom:** 6600 Workshop campaign		
Campaign			**Location:** Campaign complete: WSS62 Re-programming 12V battery sensor **Symptom:** 6600 Workshop campaign		
Campaign			**Location:** Campaign complete: ARB62 Checking HVB cell modules and re-programming BMCe software **Symptom:** 9900 Recall campaign		
DMS	27/02/2025	27/02/2025	1160770 - Porsche Zentrum Altötting	18861 km	5
Campaign			**Location:** Campaign not feasible: ARB6Z Checking HVB cell modules and re-programming BMCe software **Symptom:** 9900 Recall campaign		
Campaign			**Location:** Campaign complete: WSA11 Check high-voltage battery and replace cell block module if necessary (follow-up WRS 1) **Symptom:** 6600 Workshop campaign		
Campaign			**Location:** Campaign complete: WRW12 Re-program external communication control unit (OTA-FC) **Symptom:** 6600 Workshop campaign		
Documentation			Other		
Documentation			Other		
DMS	10/02/2025	10/02/2025	1160770 - Porsche Zentrum Altötting	16797 km	1
Documentation			Other		
DMS	17/12/2024	17/12/2024	1160770 - Porsche Zentrum Altötting	16797 km	2
Campaign			**Location:** Campaign not feasible: ARB6Z Checking HVB cell modules and re-programming BMCe software **Symptom:** 9900 Recall campaign		
Campaign			**Location:** Campaign complete: WRS11 Checking high-voltage battery and replacing cell block module if necessary **Symptom:** 6600 Workshop campaign		
DMS	24/10/2024	07/11/2024	1160770 - Porsche Zentrum Altötting	16797 km	4
Campaign			**Location:** Campaign complete: WPK05 Re-programming PSM control unit **Symptom:** 6600 Workshop campaign		
Campaign			**Location:** Campaign not feasible: WRS1Z Checking high-voltage battery and replacing cell block module if necessary **Symptom:** 6600 Workshop campaign		
Campaign			**Location:** Campaign not feasible: ARB6Z Checking HVB cell modules and re-programming BMCe software **Symptom:** 9900 Recall campaign		
Campaign			**Location:** Campaign complete: ARB0A Replacing brake hose the left and right front axle **Symptom:** 9900 Recall campaign		
DMS	18/04/2024	18/04/2024	1160770	10292 km	1
Documentation			General workshop visit / Service (DMS)		
DMS	06/02/2024	06/02/2024	1160770 - Porsche Zentrum Altötting	5424 km	1
Campaign			**Location:** Campaign complete: WPS91 Re-programming thermal management control unit (TME) **Symptom:** 6600 Workshop campaign		
DMS	21/11/2023	21/11/2023	1160770	15 km	1
Documentation			General workshop visit / Service (DMS)		
DMS	24/10/2023	26/10/2023	1160770 - Porsche Zentrum Altötting	15 km	3
Campaign			**Location:** Campaign complete: WPN82 Re-programming central computer (PCM) control unit **Symptom:** 6600 Workshop campaign		
Campaign			**Location:** Campaign complete: APB22 Check high-voltage battery and replace if necessary **Symptom:** 9900 Recall campaign		
Documentation			Other: Drucktest bestanden		
DMS	14/07/2023	02/08/2023	1160770 - Porsche Zentrum Altötting	9 km	2
Campaign			**Location:** Campaign complete: WPA81 Retrofitting electric passenger compartment heater **Symptom:** 6600 Workshop campaign		
Campaign			**Location:** Campaign complete: WNT81 Performing additional quality checks **Symptom:** 6600 Workshop campaign		

6130010 scibiorovakri Oct 2, 2026

HISTORIE OPRAV VOZIDLA V243813 **EL8 69D, Taycan 4S**

Druh zak. / č. faktury	Č. Zakázky	Založení/ Uzavření	Stav km	Cena celkem	Technik	Počet MJ/ČJ	Č. mech.
				Popis závady Pracovní pozice Materiál			
Externí SeZ	**52017731**	**17.12.2025**	**30291**	**16 189,00**	**Křemen Jiří**		
FV 5250404697		**23.12.2025**					
				0 - kontrola expirace náplně do pneumatik			
				0 - výměna brzdové kapaliny			
				0 - výměna pylového filtru			
				0 1.- Inspekce			
				0 2.- Mytí ANO			
				976819429 kabinový filtr		1,00 ks	41194
				00004321082 BRZDOVA KAPALINA		1,00 ks	41194
				G JZW021M3 OSTRIK ZIMNI 3L NA -21		1,00 ks	41194
				A0890107600 CISTIC RAPID		1,00 ks	41194
				03180000 Inspekce .		1,00 h	41150
				03560050 Dodatečné práce každé 2 rok .		1,00 h	41150
				98000001 Protokol dlouhodobé záruky karosei		1,00 h	41150
				03350000 Diagnostika vozu .		1,00 h	41150
				999999999 drobný pomocný materiál		1,00 ks	
Garanční SeZ	**52017730**	**17.12.2025**	**30291**	**27 661,00**	**Křemen Jiří**		
FV 366100001		**02.01.2026**					
				1 ARB6 Checking HVB cell modules and re-pı			
				2 WSD8 Replace electric passenger compartm			
				N 10737001 SESTIHRANNA MATICE SAM		2,00 ks	41194
				PAD963507B HVT TOPENI		1,00 ks	41194
				N 10737001 SESTIHRANNA MATICE SAM		1,00 ks	3962
				99999999 ARB69999 - akce provedena		1,00 h	41150
				99999999 WSD89999 - akce provedena		1,00 h	41150
				99999999 WSS69999 - akce provedena		1,00 h	41150
				PUJNV000 NV - WP1ZZZ9Y2SDA15118 - 1		1,00 ks	999

NEZÁVISLÝ

CERTIFIKÁT BATERIE

AVILOO
BATTERY DIAGNOSTICS

ČÍSLO CERTIFIKÁTU: AD564ED8-A214-486A-A192-B3CC0C21E8EE

VOZIDLO

ZNAČKA: Porsche
MODEL: Taycan - 83,7 kWh

STAV TACHOMETRU: 42 874 km
VIN: WP0ZZZY14PSA32093
DATUM A ČAS:
26.10.26 13:40

PROVEDL: AUTO HOLDING s.r.o.

VÝSLEDKY

Nezávislý
ZDRAVOTNÍ STAV (SOH)

93,2 %

ENERGIE 83kWh | 89kWh



DOJEZD WLTP 470km | 504km

HODNOCENÍ

SROVNÁNÍ
Jak si vaše vozidlo stojí ve srovnání se srovnatelnými vozidly?



KONTROLY

Systém řízení baterie (BMS)	✓
Snímač baterie	✓
Měření baterie	✓
Napětí článků baterie	✓
Komunikace s vozidlem	✓

SCAN FOR DETAILS

VYHODNOCENÍ

DOBRÝ STAV – NEBYLY ZJIŠTĚNY ŽÁDNÉ ANOMÁLIE

Na základě podrobné diagnostiky baterie provedené pomocí AVILOO FLASH Testu tímto potvrzujeme, že trakční baterie tohoto vozidla je v dobrém stavu.

Trakční baterie je proto oficiálně AVILOO Certified.

Dr. Marcus Berger, CEO

CARA Approved Battery Health Check

BATTERY IS TESTED AND AVILOO CERTIFIED
AVILOO CERTIFIED

ENERGIE

	Hrubá	Čistá (jmenovitá)	Využitelná
Aktuální:	87,0kWh	82,7kWh	78,0kWh
Nová:	93,4kWh	88,7kWh	83,7kWh

DOJEZD

	WLTP	Typický	Individuální
Aktuální:	357-470km	305km	276km
Nový:	383-504km	327km	297km

PROTOKOL O PROVEDENÍ

AVILOO Box připojen.	13:40:50
FLASH Test spuštěn.	✓
Sběr dat zahájen.	✓
Vozidlo detekováno.	✓
Sběr dat dokončen.	✓
Analýza dat zahájena.	✓
Analýza dat dokončena.	✓

SNÍMAČE

Snímač napětí	✓
Snímač proudu	✓
Snímače teploty	✓
Snímače napětí článků	✓

BMS

	Hodnota	Stav
Stav nabití (SoC) dle BMS*:	49%	
Přesnost výpočtu SoC:		✓
Zdravotní stav (SoH) dle BMS*:	90%	
Přesnost výpočtu SoH:		✓

MĚŘENÍ

	Min	Max	Rozdíl	Stav
Teplota baterie	8,0°C	9,0°C	1,0°C	✓
Napětí článku	3,670V	3,675V	5mV	✓
Napětí baterie	727,2V			
Průměrný proud	-2,6A			

DIAGRAM NAPĚTÍ ČLÁNKŮ

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20
1 - 20	3.672	3.673	3.672	3.672	3.673	3.672	3.672	3.672	3.672	3.672	3.672	3.673	3.674	3.674	3.675	3.673	3.673	3.674	3.674	3.673
21 - 40	3.673	3.673	3.674	3.673	3.672	3.673	3.672	3.672	3.672	3.671	3.672	3.672	3.672	3.672	3.670	3.672	3.674	3.673	3.674	3.674
41 - 60	3.673	3.673	3.673	3.672	3.672	3.673	3.674	3.672	3.673	3.673	3.672	3.673	3.672	3.673	3.672	3.672	3.673	3.672	3.672	3.672
61 - 80	3.672	3.672	3.672	3.672	3.672	3.672	3.672	3.672	3.672	3.672	3.673	3.673	3.673	3.673	3.673	3.673	3.673	3.672	3.674	3.673
81 - 100	3.673	3.674	3.674	3.673	3.673	3.673	3.672	3.673	3.673	3.674	3.672	3.672	3.672	3.672	3.672	3.673	3.672	3.672	3.672	3.671
101 - 120	3.672	3.673	3.673	3.673	3.672	3.671	3.672	3.672	3.674	3.674	3.674	3.673	3.673	3.674	3.672	3.672	3.671	3.672	3.672	3.672
121 - 140	3.672	3.673	3.674	3.673	3.672	3.673	3.673	3.673	3.672	3.673	3.673	3.674	3.674	3.673	3.672	3.672	3.673	3.673	3.673	3.673
141 - 160	3.674	3.673	3.672	3.673	3.673	3.673	3.672	3.673	3.673	3.672	3.674	3.672	3.673	3.672	3.673	3.673	3.672	3.673	3.672	3.672
161 - 180	3.673	3.673	3.675	3.673	3.672	3.672	3.673	3.673	3.673	3.673	3.674	3.673	3.673	3.672	3.673	3.673	3.673	3.673	3.673	3.673
181 - 198	3.673	3.673	3.673	3.673	3.673	3.673	3.672	3.672	3.672	3.672	3.672	3.672	3.673	3.673	3.672	3.672	3.673	3.673		



*Zde uvedené hodnoty byly načteny přímo ze systému řízení baterie (BMS) vozidla a jsou vypočteny a poskytnuty výrobcem vozidla. Zobrazený zdravotní stav (SoH) odpovídá hodnotě hlášené systémem BMS a je certifikován organizací CARA.

VYLOUČENÍ ODPOVĚDNOSTI: Výsledek testu zahrnuje aktuálně vypočtený zdravotní stav (SoH) trakční baterie. Stanovení vychází z údajů poskytnutých vozidlem. Ty jsou vyhodnocovány algoritmy společnosti AVILOO pomocí statistických a analytických modelů. Manipulace s daty v řídicí jednotce vede k nesprávnému výsledku. Uvedená hodnota SoH má technicky podmíněné rozpětí kolísání (odchylku) nejvýše 3 % u nejméně 95 % referenčních měření. Je třeba upozornit, že tato tolerance se vztahuje na stanovení SoH na úrovni článků, nikoli na SoH celé baterie. Stav nabití jednotlivých článků se totiž může lišit, což může negativně ovlivnit aktuální SoH baterie. Tyto rozdíly však lze kompenzovat pomocí systému řízení baterie (BMS) nebo během kalibrace. Výsledek odráží stav baterie v době provedení testu. Nelze z něj vyvozovat závěry o budoucím zdravotním stavu baterie. Vyjádření k mechanickému poškození nebo vnějším vlivům není součástí této diagnostiky.

AVILOO GmbH | IZ NÖ-Süd, Straße 16, Objekt 69/5 | 2355 Wiener Neudorf | Austria | business.help@aviloo.com

AD564ED8-A214-486A-A192-B3CC0C21E8EE