

Identification via VIN Identification via vehicle data Charging products



Vehicle identification number (VIN) WPOZZZY14PEA32003
Order type Taycan 4S (MY23) (Y1ADB1)
Model year 2023

Annotation: The information listed below might not be a complete vehicle history. Only jobs that have been documented within PCS5 job management (PQIS) are available. This information may not be transmitted to third parties.
Total warranty repair days (WRD): 39 Day(s)

Filter settings

☐ Workshop/Recall campaign ☐ OTA campaign ☐ Repair ☐ Maintenance/Inspection ☐ Documentation

Expand all

Status	Repair Start	Repair End	Dealer	Mileage	
	18/12/2025	18/12/2025	6130010 - Porsche Center Prague	30291 km	
		Location: Campaign not feasible: WSS6Z Re-programming 12V battery sensor Symptom: 6600 Workshop campaign			
		Location: Campaign not feasible: WSD8Z Replace electric passenger compartment heater Symptom: 6600 Workshop campaign			
		Location: Campaign not feasible: ARB6Z Checking HV/B cell modules and re-programming BMCE software Symptom: 9900 Recall campaign			
		Location: Maintenance			
		Location: Maintenance: Výměna pyl. filtru, brz. kapaliny.			
	18/12/2025	18/12/2025	6130010 - Porsche Center Prague	30291 km	
		Location: Campaign complete: WSD8Z Replace electric passenger compartment heater Symptom: 6600 Workshop campaign			
		Location: Campaign complete: WSS6Z Re-programming 12V battery sensor Symptom: 6600 Workshop campaign			
		Location: Campaign complete: ARB6Z Checking HV/B cell modules and re-programming BMCE software Symptom: 9900 Recall campaign			
	27/02/2025	27/02/2025	1160770 - Porsche Zentrum Alttötting	18861 km	
		Location: Campaign not feasible: ARB6Z Checking HV/B cell modules and re-programming BMCE software Symptom: 9900 Recall campaign			
		Location: Campaign complete: WSA11 Check high-voltage battery and replace cell block module if necessary (follow-up WRS 1) Symptom: 6600 Workshop campaign			
		Location: Campaign complete: WRW12 Re-program external communication control unit (OTA-FC) Symptom: 6600 Workshop campaign			
		Location: Other			
		Location: Other			
	10/02/2025	10/02/2025	1160770 - Porsche Zentrum Alttötting	16797 km	
		Location: Other			
	17/12/2024	17/12/2024	1160770 - Porsche Zentrum Alttötting	16797 km	
		Location: Campaign not feasible: ARB6Z Checking HV/B cell modules and re-programming BMCE software Symptom: 9900 Recall campaign			
		Location: Campaign complete: WRS11 Checking high-voltage battery and replacing cell block module if necessary Symptom: 6600 Workshop campaign			
	24/10/2024	07/11/2024	1160770 - Porsche Zentrum Alttötting	16797 km	
		Location: Campaign complete: WPK05 Re-programming PSM control unit Symptom: 6600 Workshop campaign			
		Location: Campaign not feasible: WRS1Z Checking high-voltage battery and replacing cell block module if necessary Symptom: 6600 Workshop campaign			
		Location: Campaign not feasible: ARB6Z Checking HV/B cell modules and re-programming BMCE software Symptom: 9900 Recall campaign			
		Location: Campaign complete: ARB0A Replacing brake hose the left and right front axle Symptom: 9900 Recall campaign			
	18/04/2024	18/04/2024	1160770	10292 km	
		Location: General workshop visit / Service (DMS)			
	06/02/2024	06/02/2024	1160770 - Porsche Zentrum Alttötting	5424 km	
		Location: Campaign complete: WPS91 Re-programming thermal management control unit (TME) Symptom: 6600 Workshop campaign			
	21/11/2023	21/11/2023	1160770	15 km	
		Location: General workshop visit / Service (DMS)			
	24/10/2023	26/10/2023	1160770 - Porsche Zentrum Alttötting	15 km	
		Location: Campaign complete: WPN8Z Re-programming central computer (PCM) control unit Symptom: 6600 Workshop campaign			
		Location: Campaign complete: APB2Z Check high-voltage battery and replace if necessary Symptom: 9900 Recall campaign			
		Location: Other: Drucktest bestanden			
	14/07/2023	02/08/2023	1160770 - Porsche Zentrum Alttötting	9 km	
		Location: Campaign complete: WPA81 Retrofitting electric passenger compartment heater Symptom: 6600 Workshop campaign			
		Location: Campaign complete: WNT81 Performing additional quality checks Symptom: 6600 Workshop campaign			

HISTORIE OPRAV VOZIDLA V243813

EL8 69D, Taycan 4S

Druh zak. č. faktury	Č. Zakázky	Založení/ Uzavření	Stav km	Cena celkem	Technik	Počet MJ/ČJ Č. mech.
			Popis závady Pracovní pozice Materiál			
Externí SeZ FV 5250404697	52017731	17.12.2025 23.12.2025	30291	16 189,00	Křemen Jiří	
			0 - kontrola expirace náplně do pneumatik			
			0 - výměna brzdové kapaliny			
			0 - výměna pylového filtru			
			0 1.- Inspekce			
			0 2.- Mytí ANO			
			976819429 kabinový filtr	1,00 ks		41194
			00004321082 BRZDOVA KAPALINA	1,00 ks		41194
			G JZW021M3 OSTRIK ZIMNI 3L NA -21	1,00 ks		41194
			A0890107600 CISTIC RAPID	1,00 ks		41194
			03180000 Inspekce .	1,00 h		41150
			03560050 Dodatečné práce každé 2 rok .	1,00 h		41150
			98000001 Protokol dlouhodobé záruky karoser	1,00 h		41150
			03350000 Diagnostika vozu .	1,00 h		41150
			999999999 drobný pomocný materiál	1,00 ks		
Garanční SeZ FV 366100001	52017730	17.12.2025 02.01.2026	30291	27 661,00	Křemen Jiří	
			1 ARB6 Checking HVB cell modules and re-p			
			2 WSD8 Replace electric passenger compartm			
			N 10737001 SESTIHRANNA MATICE SAM	2,00 ks		41194
			PAD963507B HVT TOPENI	1,00 ks		41194
			N 10737001 SESTIHRANNA MATICE SAM	1,00 ks		3962
			999999999 ARB69999 - akce provedena	1,00 h		41150
			999999999 WSD89999 - akce provedena	1,00 h		41150
			999999999 WSS69999 - akce provedena	1,00 h		41150
			PUJNV000 NV - WP1ZZZ9Y2SDA15118 - 1	1,00 ks		999