

# Vehicle data

1	WVG DE2	AX 7	GW054781						
2	5N2	3V3	TR+ST						
3	Tiguan 2.0	147 KW TSI	A6A						
	CAMB	LI7FL	QNR						
			XU						
4	B0M	C5H	G0R	H4C	J1L	D2L			
	-	1AT	1G9	2PP	1NT	5RT	5SR	TQ2	
	0BE	3S1	3U1	QG2	8AY	8GU	8ZH		
	1KU	1LJ	3FU	G03	0GG				
	0Y2	4UF	4X3	4I3	N7D	5MB			
	8RM	2JK	E0A	0AK	0BE	2UC		2G1	
	1JK	L10	0YG						

Fig. 1: 1: Vehicle identification number; 2: Vehicle type, engine power, gearbox type; 3: Engine code, gear box code, paint number, interior equipment; 4: Optional extras, PR numbers.

Delivery inspection carried out on: 06/01/16	Date of delivery to customer / initial registration: 06-2016
Volkswagen dealership stamp	Volkswagen dealership stamp

a) Whichever comes first.

# The Volkswagen service

## Which vehicles does this service schedule cover?

- This service schedule covers the following vehicles:
- CC
  - Eos
  - Golf
  - Golf Cabriolet
  - Golf GTD
  - Golf GTE
  - Golf GTI
  - Golf SV
  - Golf Estate
  - Jetta
  - Passat
  - Passat GTE
  - Passat Estate
  - Passat Estate GTE
  - Polo
  - Scirocco
  - Sharan
  - The Beetle
  - The Beetle Cabriolet
  - Tiguan
  - Touareg
  - Touran
  - up!

## The importance of this service schedule

The vehicle data (Fig. 1) attached to the inside cover of this service schedule help ensure that you can have the correct Volkswagen Genuine Parts® installed in your vehicle whenever required. They also determine which type of service applies to your vehicle.

- The service schedule confirms when the vehicle was first registered or delivered, when the delivery inspection was carried out, and thus the date from which your vehicle is covered by our warranty.
- The service schedule informs you when which service is due. The work to be carried out varies from vehicle to vehicle, but a qualified workshop will be able to explain exactly what work needs to be done.
- Your qualified workshop will document any service-related work in the service schedule.

Your service schedule should be kept in the vehicle wallet to ensure that it is at hand when you need it. Please remember to give this service schedule to the new owner if you sell your car.

**WARNING**

Inadequate servicing, no servicing at all, or failure to adhere to service intervals may result in breakdowns, accidents or serious injury.

- Have your car serviced by a qualified workshop.
- Observe the owner's manual.

**NOTICE**

Volkswagen is not responsible for any vehicle damage caused by low-quality fuel, the wrong oil standard, inadequate servicing work or lack of availability of parts.

Regular servicing of your vehicle not only maintains its value, it also ensures that your vehicle remains roadworthy and in working order. Servicing work should therefore be carried out in accordance with the maintenance table. Your qualified workshop will be happy to advise you.

**Ensure Service at VW Dealership every 15000 Km/ every year (Whichever earlier). Failure to perform timely service would void warranty.**




**Proof of service 1**

Yes / No. The following work was carried out:	Yes / No. Additional work - Change of:
<input checked="" type="checkbox"/> Oil change service	<input checked="" type="checkbox"/> AdBlue®
<input checked="" type="checkbox"/> Inspection	<input checked="" type="checkbox"/> Brake fluid
<input checked="" type="checkbox"/> With oil change	<input checked="" type="checkbox"/> Diesel fuel filter
<input checked="" type="checkbox"/> With extended scope of inspection	<input checked="" type="checkbox"/> Gearbox oil: DSG®, ATF
<input checked="" type="checkbox"/> LongLife engine oil used	<input checked="" type="checkbox"/> Haldex coupling: oil
<input checked="" type="checkbox"/> Corrosion and leak checks of the natural gas system	<input checked="" type="checkbox"/> Poly V-belt
<input checked="" type="checkbox"/> Check of headlight settings	<input checked="" type="checkbox"/> Air filter insert
<input checked="" type="checkbox"/> Repairs recommended	<input checked="" type="checkbox"/> Tyre filler bottle (sealant)
<input checked="" type="checkbox"/> Customer request (this should also be noted on the order)	<input checked="" type="checkbox"/> Dust and pollen filter insert
Service carried out on: 4/7/17	<input checked="" type="checkbox"/> Toothed belt
at km/miles: 1600	<input checked="" type="checkbox"/> Spark plugs
Invoice number: 115-111111	<input checked="" type="checkbox"/> ..... <input checked="" type="checkbox"/> .....
Service carried out by: 	LongLife mobility guarantee:
Stamp of qualified workshop	Volkswagen dealership stamp

<b>Your next services</b>
<b>Service event</b>
<input type="checkbox"/> as per Service interval display
or on (Date): July 2018
or at (km/miles): 30 000

**Documentation of the body check**



**Fig. 3** Illustration valid for all vehicles and body designs.

Your qualified workshop will indicate damage in Fig. 3 using the following symbols:

- ✖ Scratches
- Dents
- Corrosion
- △ Stone chipping


<b>Any damage?</b>	<b>Yes:</b> <input type="checkbox"/>	<b>No:</b> <input type="checkbox"/>
Description of damage:		
Stamp of qualified workshop		

3G001Z720SC

**Proof of service 2**

Yes / No. The following work was carried out:	Yes / No. Additional work - Change of:
<input type="checkbox"/> Oil change service	<input type="checkbox"/> AdBlue®
<input checked="" type="checkbox"/> Inspection	<input checked="" type="checkbox"/> Brake fluid
<input checked="" type="checkbox"/> With oil change	<input type="checkbox"/> Diesel fuel filter
<input type="checkbox"/> With extended scope of inspection	<input type="checkbox"/> Gearbox oil: DSG®, ATF
<input type="checkbox"/> LongLife engine oil used	<input checked="" type="checkbox"/> Haldex coupling: oil
<input type="checkbox"/> Corrosion and leak checks of the natural gas system	<input checked="" type="checkbox"/> Poly V-belt
<input type="checkbox"/> Check of headlight settings	<input checked="" type="checkbox"/> Air filter insert
<input type="checkbox"/> Repairs recommended	<input checked="" type="checkbox"/> Tyre filler bottle (sealant)
<input type="checkbox"/> Customer request (this should also be noted on the order)	<input checked="" type="checkbox"/> Dust and pollen filter insert
Service carried out on: 23/4/18	<input checked="" type="checkbox"/> Toothed belt
at km/miles: 30756	<input type="checkbox"/> Spark plugs
Invoice number:	<input type="checkbox"/> ..... LongLife mobility guarantee:
Service carried out by:	Volkswagen dealership stamp
Stamp of qualified workshop	Additional work
Your next services	.....
Service event	on (Date): ..... or
as per Service interval display	at (km/miles): ..... 45000

**Documentation of the body check**



**Fig. 4** Illustration valid for all vehicles and body designs.

Your qualified workshop will indicate damage in Fig. 4 using the following symbols:

- Scratches
- Dents
- Corrosion
- Stone chipping

Any damage?	Yes: <input type="checkbox"/>	No: <input type="checkbox"/>
Description of damage:		
Stamp of qualified workshop		


3G0012720SC

**Proof of service 3**

Yes / No. The following work was carried out:	Yes / No. Additional work - Change of:
<input checked="" type="checkbox"/> Oil change service	<input checked="" type="checkbox"/> AdBlue®
<input type="checkbox"/> Inspection	<input checked="" type="checkbox"/> Brake fluid
<input type="checkbox"/> With oil change	<input type="checkbox"/> Diesel fuel filter
<input type="checkbox"/> With extended scope of inspection	<input type="checkbox"/> Gearbox oil: DSG®, ATF
<input type="checkbox"/> LongLife engine oil used	<input type="checkbox"/> Haldex coupling: oil
<input type="checkbox"/> Corrosion and leak checks of the natural gas system	<input type="checkbox"/> Poly V-belt
<input type="checkbox"/> Check of headlight settings	<input type="checkbox"/> Air filter insert
<input type="checkbox"/> Repairs recommended	<input type="checkbox"/> Tyre filler bottle (sealant)
<input type="checkbox"/> Customer request (this should also be noted on the order)	<input type="checkbox"/> Dust and pollen filter insert
Service carried out on: <b>22/4/2019</b>	<input type="checkbox"/> Toothed belt
at km/miles: <b>46797</b>	<input type="checkbox"/> Spark plugs
Invoice number: <b>2019-01-01</b>	<input type="checkbox"/> ..... <input type="checkbox"/> .....
Service carried out by: 	LongLife mobility guarantee:
Stamp of qualified-workshop: 	Volkswagen dealership stamp

<b>Your next services</b>
<b>Service event</b>
<input type="checkbox"/> as per Service interval display
or
on (Date): <b>4/2020</b>
or
at (km/miles): <b>61,000</b>

**Documentation of the body check**



**Fig. 5** Illustration valid for all vehicles and body designs.



Your qualified workshop will indicate damage in Fig. 5 using the following symbols:

- \* Scratches
- Dents
- Corrosion
- △ Stone chipping

<b>Any damage?</b>	<b>Yes:</b> <input type="checkbox"/>	<b>No:</b> <input type="checkbox"/>
Description of damage:		
Stamp of qualified workshop		


3G001Z720SC

**Proof of service 4**

<b>Yes / No. The following work was carried out:</b>	<b>Yes / No. Additional work - Change of:</b>
<input type="checkbox"/> Oil change service	<input type="checkbox"/> AdBlue®
<input checked="" type="checkbox"/> Inspection	<input type="checkbox"/> Brake fluid
<input checked="" type="checkbox"/> With oil change	<input type="checkbox"/> Diesel fuel filter
<input type="checkbox"/> With extended scope of inspection	<input type="checkbox"/> Gearbox oil: DSG®, ATF
<input type="checkbox"/> LongLife engine oil used	<input type="checkbox"/> Haldex coupling: oil
<input type="checkbox"/> Corrosion and leak checks of the natural gas system	<input type="checkbox"/> Poly V-belt
<input type="checkbox"/> Check of headlight settings	<input type="checkbox"/> Air filter insert
<input type="checkbox"/> Repairs recommended	<input type="checkbox"/> Tyre filler bottle (sealant)
<input type="checkbox"/> Customer request (this should also be noted on the order)	<input type="checkbox"/> Dust and pollen filter insert
Service carried out on: <b>01-2-2020</b>	<input type="checkbox"/> Toothed belt
at km/miles: <b>61675</b>	<input type="checkbox"/> Spark plugs
Invoice number: .....	<input type="checkbox"/> .....
Service carried out by: 	LongLife mobility guarantee: .....
Stamp of qualified workshop: 	Volkswagen dealership stamp

<b>Your next services</b>
<b>Service event</b>
<input type="checkbox"/> as per Service interval display
or
on (Date): <b>02.2021</b>
or
at (km/miles): <b>76000</b>

**Documentation of the body check**



**Fig. 6** Illustration valid for all vehicles and body designs.

Your qualified workshop will indicate damage in Fig. 6 using the following symbols:

- ✖ Scratches
- Dents
- Corrosion
- △ Stone chipping

<b>Any damage?</b>	<b>Yes:</b> <input type="checkbox"/>	<b>No:</b> <input type="checkbox"/>
Description of damage:		
Stamp of qualified workshop		

3G0012720SC

**Proof of service 5**

Yes / No. The following work was carried out:	Yes / No. Additional work - Change of:
<input checked="" type="checkbox"/> Oil change service	<input type="checkbox"/> AdBlue®
<input checked="" type="checkbox"/> Inspection	<input checked="" type="checkbox"/> Brake fluid
<input type="checkbox"/> With oil change	<input type="checkbox"/> Diesel fuel filter
<input type="checkbox"/> With extended scope of inspection	<input type="checkbox"/> Gearbox oil: DSG®, ATF
<input checked="" type="checkbox"/> LongLife engine oil used	<input type="checkbox"/> Haldex coupling: oil
<input type="checkbox"/> Corrosion and leak checks of the natural gas system	<input type="checkbox"/> Poly V-belt
<input checked="" type="checkbox"/> Check of headlight settings	<input checked="" type="checkbox"/> Air filter insert
<input type="checkbox"/> Repairs recommended	<input type="checkbox"/> Tyre filler bottle (sealant)
<input type="checkbox"/> Customer request (this should also be noted on the order)	<input type="checkbox"/> Dust and pollen filter insert
Service carried out on: <b>2.8.2021</b>	<input type="checkbox"/> Toothed belt
at km/miles: <b>72080</b>	<input checked="" type="checkbox"/> Spark plugs
Invoice number: <b>.....</b>	<input type="checkbox"/> ..... LongLife mobility guarantee:
Service carried out by:  <b>LUBOŠ ZIMMEL - OPRAVY SILNIČNÍCH VOZIDEL K LAVICE 88, PRAHA 6, IČO: 16472594</b>	Volkswagen dealership stamp
Stamp of qualified workshop	
<b>Your next services</b>	<b>Additional work</b>
<input type="checkbox"/> as per Service interval display	.....
or	on (Date): .....
on (Date): <b>08/22</b>	or
or	at (km/miles): .....
at (km/miles): <b>87000</b>	Stamp of qualified workshop

3G0012720SC

**Documentation of the body check**




Fig. 7 Illustration valid for all vehicles and body designs.

Your qualified workshop will indicate damage in Fig. 7 using the following symbols:

✘ Scratches    ○ Dents    □ Corrosion    △ Stone chipping


Any damage?	Yes: <input type="checkbox"/>	No: <input type="checkbox"/>
Description of damage:		
Stamp of qualified workshop		

**Proof of service 6**

Yes / No. The following work was carried out:	Yes / No. Additional work - Change of:
<input checked="" type="checkbox"/> Oil change service	<input type="checkbox"/> AdBlue®
<input checked="" type="checkbox"/> Inspection	<input type="checkbox"/> Brake fluid
<input type="checkbox"/> With oil change	<input type="checkbox"/> Diesel fuel filter
<input type="checkbox"/> With extended scope of inspection	<input type="checkbox"/> Gearbox oil: DSG®, ATF
<input checked="" type="checkbox"/> LongLife engine oil used	<input checked="" type="checkbox"/> Haldex coupling: oil
Corrosion and leak checks of the natural gas system	<input type="checkbox"/> Poly V-belt
<input checked="" type="checkbox"/> Check of headlight settings	<input checked="" type="checkbox"/> Air filter insert
<input type="checkbox"/> Repairs recommended	<input type="checkbox"/> Tyre filler bottle (sealant)
<input type="checkbox"/> Customer request (this should also be noted on the order)	<input type="checkbox"/> Dust and pollen filter insert
Service carried out on: <b>14.7.2022</b>	<input type="checkbox"/> Toothed belt
at km/miles: <b>85970</b>	<input type="checkbox"/> Spark plugs
Invoice number: .....	<input type="checkbox"/> <b>Stěrač př. + zad</b>
Service carried out by:	<input type="checkbox"/> ..... LongLife mobility guarantee:
	
<b>LUBOŠ ZIMMEL, OPRAVA SILNIČNÍCH VOZIDEL K. LAJEVE 16, PRAHA 6, IČO: 16472594</b>	Volkswagen dealership stamp
Stamp of qualified workshop	

<b>Your next services</b>	<b>Additional work</b>
<input type="checkbox"/> as per Service interval display	.....
or	on (Date): .....
on (Date): <b>7/2023</b>	or
or	at (km/miles): .....
at (km/miles): <b>101000</b>	

**Documentation of the body check**



**Fig. 8** Illustration valid for all vehicles and body designs.

Your qualified workshop will indicate damage in Fig. 8 using the following symbols:

- ✖ Scratches
- Dents
- Corrosion
- △ Stone chipping

<b>Any damage?</b>	<b>Yes:</b> <input type="checkbox"/>	<b>No:</b> <input type="checkbox"/>
Description of damage:		
Stamp of qualified workshop		

3G0012720SC

**Proof of service 7**

Yes / No. The following work was carried out:	Yes / No. Additional work - Change of:
<input checked="" type="checkbox"/> Oil change service	<input type="checkbox"/> AdBlue®
<input checked="" type="checkbox"/> Inspection	<input type="checkbox"/> Brake fluid
<input type="checkbox"/> With oil change	<input type="checkbox"/> Diesel fuel filter
<input type="checkbox"/> With extended scope of inspection	<input type="checkbox"/> Gearbox oil: DSG®, ATF
<input checked="" type="checkbox"/> LongLife engine oil used	<input type="checkbox"/> Haldex coupling: oil
<input type="checkbox"/> Corrosion and leak checks of the natural gas system	<input type="checkbox"/> Poly V-belt
<input checked="" type="checkbox"/> Check of headlight settings	<input checked="" type="checkbox"/> Air filter insert
<input type="checkbox"/> Repairs recommended	<input type="checkbox"/> Tyre filler bottle (sealant)
<input type="checkbox"/> Customer request (this should also be noted on the order)	<input type="checkbox"/> Dust and pollen filter insert
Service carried out on: <b>29.6.2023</b>	<input type="checkbox"/> Toothed belt
at km/miles: <b>96200</b>	<input type="checkbox"/> Spark plugs
Invoice number: .....	<input type="checkbox"/> <b>OE+VF+PK</b>
Service carried out by:	<input type="checkbox"/> ..... LongLife mobility guarantee:
  	
<b>LUBOŠ ZIMMEL</b> <small>OPRAVA SILNIČNÍCH VOZIDEL</small> <b>K LÁVCE 38, PRAHA 6, IČO: 16472594</b>	<b>K LÁVCE 38, PRAHA 6, IČO: 16472594</b>
Stamp of qualified workshop	Volkswagen dealership stamp

<b>Your next services</b>	<b>Additional work</b>
<input type="checkbox"/> as per Service interval display	.....
or	on (Date): .....
on (Date): <b>6/2024</b>	or
or	at (km/miles): .....
at (km/miles): <b>111 000</b>	Stamp of qualified workshop

3G001Z720SC

**Documentation of the body check**




Fig. 9 Illustration valid for all vehicles and body designs.

Your qualified workshop will indicate damage in Fig. 9 using the following symbols:

- ✱ Scratches
- Dents
- Corrosion
- △ Stone chipping


<b>Any damage?</b>	Yes: <input type="checkbox"/> No: <input type="checkbox"/>
Description of damage:	
Stamp of qualified workshop	

**Proof of service 8**

Yes / No. The following work was carried out:	Yes / No. Additional work - Change of:
<input checked="" type="checkbox"/> Oil change service	<input type="checkbox"/> AdBlue®
<input checked="" type="checkbox"/> Inspection	<input checked="" type="checkbox"/> Brake fluid
<input type="checkbox"/> With oil change	<input type="checkbox"/> Diesel fuel filter
<input type="checkbox"/> With extended scope of inspection	<input type="checkbox"/> Gearbox oil: DSG®, ATF
<input checked="" type="checkbox"/> LongLife engine oil used	<input type="checkbox"/> Haldex coupling: oil
Corrosion and leak checks of the natural gas system	<input type="checkbox"/> Poly V-belt
<input checked="" type="checkbox"/> Check of headlight settings	<input checked="" type="checkbox"/> Air filter insert
<input type="checkbox"/> Repairs recommended	<input type="checkbox"/> Tyre filler bottle (sealant)
<input type="checkbox"/> Customer request (this should also be noted on the order)	<input checked="" type="checkbox"/> Dust and pollen filter insert
Service carried out on: 30.5.2024	<input type="checkbox"/> Toothed belt
at km/miles: 109 800	<input type="checkbox"/> Spark plugs
Invoice number: .....	<input type="checkbox"/> .....
Service carried out by:	LongLife mobility guarantee:
LUBOS ZIZKA, PRAHA 6, IČO: 16472594	K. LAVCE 38, PRAHA 6, IČO: 16472594
Stamp of qualified workshop	Volkswagen dealership stamp

<b>Your next services</b>	<b>Additional work</b>
<input type="checkbox"/> as per Service interval display	
or	
on (Date): 5/2025	Date): Metacabo
or	or
at (km/miles): 130 000	at (km/miles): .....

**Documentation of the body check**



**Fig. 10** Illustration valid for all vehicles and body designs.

Your qualified workshop will indicate damage in Fig. 10 using the following symbols:

- ✱ Scratches
- Dents
- Corrosion
- △ Stone chipping

<b>Any damage?</b>	<b>Yes:</b> <input type="checkbox"/>	<b>No:</b> <input type="checkbox"/>
Description of damage:		
Stamp of qualified workshop		

3G001Z7Z05C

