



ONLINE SERVICE HISTORY

Customer Copy






VEHICLE DETAILS

VIN: SALYA2BK5KA211503
MODEL: Range Rover Velar / L560
ENGINE: 3.0L Diesel
COLOUR: AMMONITE GREY/CORRIS GREY
WARRANTY START DATE: 02/05/2019

REGISTRATION COUNTRY:
Not present

Please note that service intervals always represent the maximum time and distance that should exist between servicing. Driving style and conditions may necessitate earlier servicing as indicated by the notifications on your instrument panel.

SERVICE HISTORY

REPAIRER	JOB NUMBER	JOB DATE	ODOMETER	DETAILS
Albion Cars s.r.o. K Chotobuzi 333 estlice Stredoceský 251 01 Czech Republic	BL20221586 	13/09/2022	107,994 km	Scheduled Service Completed 104,000 km/ 48 months service Related Service Items Renewal of Oil and Oil Filter Renewal of Pollen Filter Renewal of Engine Air Filter Renewal of Fuel Filter AdBlue Top-up (Diesel exhaust fluid)
Albion Cars s.r.o. K Chotobuzi 333 estlice Stredoceský 251 01 Czech Republic	BL20220105 	14/01/2022	81,659 km	Scheduled Service Completed 78,000 km/ 36 months service Related Service Items Renewal of Oil and Oil Filter Renewal of Pollen Filter Renewal of Brake Fluid Replace Wiper Blades
Albion Cars s.r.o. K Chotobuzi 333 estlice Stredoceský 251 01 Czech Republic	BL20210184 	12/02/2021	55,082 km	Scheduled Service Completed 52,000 km/ 24 months service Related Service Items Renewal of Oil and Oil Filter Renewal of Pollen Filter Renewal of Engine Air Filter Renewal of Fuel Filter Replace Wiper Blades
Albion Cars s.r.o. K Chotobuzi 333 estlice Stredoceský 251 01 Czech Republic	BL20201733 	15/01/2021	47,546 km	Scheduled Service Completed Oil Service Related Service Items Renewal of Oil and Oil Filter
Albion Cars spol. s.r.o. V Oblouku 727 Pruhonice Stredoceský 252 43 Czech Republic	BL20200225 	13/02/2020	20,785 km	Scheduled Service Completed 26,000 km/ 12 months service Related Service Items Renewal of Oil and Oil Filter Replace Wiper Blades



ONLINE SERVICE HISTORY

Customer Copy

VEHICLE DETAILS

VIN: SALYA2BK5KA211503
MODEL: Range Rover Velar / L560
ENGINE: 3.0L Diesel
COLOUR: AMMONITE GREY/CORRIS GREY
WARRANTY START DATE: 02/05/2019

REGISTRATION COUNTRY:
Not present

Please note that service intervals always represent the maximum time and distance that should exist between servicing. Driving style and conditions may necessitate earlier servicing as indicated by the notifications on your instrument panel.

SERVICE HISTORY

REPAIRER	JOB NUMBER	JOB DATE	ODOMETER	DETAILS
Albion Cars spol. s.r.o. V Oblouku 727 Prhonice Stedoeský 252 43 Czech Republic	20180389 	29/01/2019	12 km	Scheduled Service Completed Pre-Delivery Inspection Related Service Items Not Applicable